

# PAT Report Fail

## For all Sites and Locations



CLIENT DETAILS	
<b>Company Name:</b>	RSR Systems Ltd
<b>Address:</b>	Waterside House Falmouth Road Penryn Cornwall TR10 8BE

DETAIL OF CONTRACTOR RESPONSIBLE FOR TESTING		
<b>Company Name:</b>	PAT Serve Electrical Safety	
<b>Address:</b>	Waterside House Falmouth Road Penryn Cornwall TR10 8BD	<b>Telephone:</b> 01326 378268
		<b>Mobile:</b> 0777 9999999
		<b>Email:</b> support@simplypats.co.uk
<b>Order Number:</b>	RSR0001/FEB	<b>Signature:</b> <i>Your Signature</i>
<b>File Name:</b>	Example File.PAT	

APPLIANCE DETAILS AND TEST RESULTS									
Key P = PASS / F = FAIL / S = SKIP (or test not applicable)									
Appliance Id	Appliance Description	Test Date	Visual	Polarity	Earth Continuity (Ohms)	Insulation (MOhms)	Load (kVA)	Overall Status	
<b>BUILDING 1 - ROOM 1</b>									
AP004	MICROWAVE FAIL ON MICROWAVE TEST SEE REPORT	04/02/11	P	S	P 0.07	P >200	P 1.37	FAIL	
AP0023	3KW HEATER FAILED ON BOND	04/02/11	P	S	F >19.99	S	S	FAIL	
AP0027	MICROWAVE DAMAGED CONNECTION TO APPLIANCE - REWIRE / REPAIR	04/02/11	F	S	S	S	S	FAIL	
AP0028	EXT LEAD FAILED POLARITY	04/02/11	P	F	P 0.06	P >200	S	FAIL	
AP0029	EXT LEAD REVERSED POLARITY - DISCARD	04/02/11	P	F	P 0.06	P >200	S	FAIL	
AP0030	EXT LEAD FAILED POLARITY	04/02/11	P	F	P 0.06	P >200	S	FAIL	
								Total Appliances >	6
<b>BUILDING 1 - ROOM 2</b>									
AP0031	EXT LEAD DOUBLE REVERSED POLARITY - DISCARD	04/02/11	P	F	P 0.17	P >200	S	FAIL	
AP0032	MICROWAVE FAILED POLARITY	04/02/11	P	F	P 0.21	P >200	S	FAIL	
AP0033	EXT LEAD QUAD FAILED POLARITY	04/02/11	P	F	P 0.26	P >200	S	FAIL	
AP0034	EXT LEAD 5 FAILED POLARITY	04/02/11	P	F	P 0.31	P >200	S	FAIL	
AP0035	EXT LEAD LONG REVERSED POLARITY - DISCARD	04/02/11	P	F	P 0.44	P >200	S	FAIL	
								Total Appliances >	5

**APPLIANCE DETAILS AND TEST RESULTS**

**Key**  
 P = PASS / F = FAIL / S = SKIP (or test not applicable)

Appliance Id	Appliance Description	Test Date	Visual	Polarity	Earth Continuity (Ohms)	Insulation (MOhms)	Load (kVA)	Overall Status
<b>BUILDING 4 - ROOM 1C</b>								
AP0036	LAMP FAILED ON EARTH BOND	04/02/11	P	S	F 0.12	P >200	S	FAIL
AP0040	IT EQUIPMENT CLASS1 FAIL ON BOND	04/02/11	P	S	F 0.67	P >200	S	FAIL
AP0044	EXT LEAD REVERSED POLARITY - DISCARD	04/02/11	P	F	P 0.05	P >200	S	FAIL
Total Appliances >								<b>3</b>
<b>BUILDING 4 - ROOM 2</b>								
AP0045	EXT LEAD REVERSED POLARITY - DISCARD	04/02/11	P	F	P 0.05	P >200	S	FAIL
AP0046	ADDED HERE EARTH CONTINUITY FAIL - REWIRE / SERVICE / REPAIR OR DISCARD	04/02/11	P	F	P 0.05	P >200	S	FAIL
Total Appliances >								<b>2</b>
<b>Total Appliances For Report:</b>								<b>16</b>