

Report Of Failed Appliances
For all Sites and Locations

Mr Brown Joe
RSR Systems Ltd
Waterside House
Falmouth Road
Penryn
Cronwall
TR10 8BD
ron@simplypats.co.uk



SimplyPats PAT Testing Services
Waterside House
Falmouth Road
Penryn
Cornwall
TR10 8BD
Phone: 01326 378268
Mobile: 07775 000000
Email: support@simplypats.co.uk

Appliance Description	Appliance Id	Test Date	Vis	Pol	Earth Cont Ohms	Insulation MOhms	Load kVA	Leakage mA	Touch Leak mA	Sub Leak mA	Flash mA
RSR SYSTEMS - GENERAL OFFICE											
POWER LEAD CABLE HAS A SPLIT IN IT	E01079756	05/11/09	F	P	0.08 P	50.00 P	S	S	S	S	S
Total Appliances:											1
RSR SYSTEMS - TRAINING ROOM											
LUMINAIRE CRACKED OUTER CASING	E01079775	05/11/09	F	S	S	50.00 P	<0.05 P	<0.10 P	S	S	S
POWER LEAD OUTER CASING DAMAGED	E02012554	05/11/09	F	P	0.11 P	50.00 P	S	S	S	S	S
Total Appliances:											2
Total Appliances For Report:											3